

Ministry of Environment Inspection Record

Environmental Protection Division

EP System:				
<u>AMS</u>	Inspection Status: FINAL	Inspection Status: FINAL		
System Number:	Inspection No:	Inspection No:		
11678	17765			
EP System Status: <u>Active</u>	Inspection Date: 2014-08	Inspection Date: 2014-08-04		
Region:				
<u>Cariboo</u>	Office: Williams Lake			
Trigger: Planned Inci	dents of Non-Compliance	Observed: Yes		
Non-Compliance Decision Matrix Level: Level 4	Non-Compliance Decision Matrix Category: Category B			
Inspector Name(s):		Risk Ranking:		
Jack Green		<u>1 to 2 = Medium</u>		
	Total Non-Compliance(s):			
Audit:	2			
Regulated Party:				
Mount Polley Mining Corporation				
Regulated Party Contact(s):				
Colleen Hughes				
Mailing Address: P.O. BOX 12 LIKELY, BC VOL 1N0				
Phone No: (250)790-2215	Fax No:			
Contact Email: chughes@mountpolley.com				
Location Description or Site Address:				
Mount Polley is an open pit copper/gold mine loc	cated near Likely BC.			
Latitude: 52.54547 N	Longitude: 121.63433	W		
Receiving Environment(s): Surfacewater				

Summary

MONITORING AND REPORTING REQUIREMENTS				
Inspection Period:				
From: 2014-08-04	To: 2014-08-05			
Requirement Source: Permit				
Activity: Office Review		Waste Type: Effluent		
Inspection Summary: Failure of tailings dam at approximately 3:00am on 4 August 2014 resulted in large quantities of tailings material flowing into Polley Lake, Hazeltine Creek and Quesnel Lake. Response: Order				
ACTIONS REQUIRED BY REGULATED PARTY:				
See Pollution Abatement Order.				
ADDITIONAL COMMENTS:				

Inspection Details

Compliance Summary

Requirement Type: Discharge

Requirement Description:

2.2 Bypasses

Discharge

Operations

The discharge of effluent which has bypassed the designated treatment works is prohibited unless the approval of the Director is obtained and confirmed in writing.

In

0

0

Out

1

N/A

0

0

N/D

0

0

Details/Findings: Due to the unexpected nature of the discharge, no approval was obtained by the Director.						
Compliance: O	<u>ut</u>					
Requirement [*]	Гуре: <u>Operations</u>					
structures and	tation of watercou facilities. The Dire of watercourses ca	ctor may specify	and require im	plementation	and operation of any mine on of measures to prevent es on site.	
The tailings da and Quesnel L	am failure of Augus ake.	st 4 2014 caused	massive sedim	entation of	Hazeltine Creek, Polley lake	
Compliance: O						
	wing collected d		n:			
Samples? U	specify)	EMS No.				
Is the Inspect	ion related to an	EA Project?	EA Project Co	ertificate N	lumber:	
INSPECTION COI	NDUCTED BY:					
Signature					Date Signed	
Jack Green					2014-10-03	
ENCLOSURE(S) 7	O REGULATED PART	Y & DESCRIPTION	:			
					0.420 4 1:	
REGULATORY CO	NSIDERATIONS:				<u>CVIS Archive</u>	
DIGGLATIAED						
Please note that sections of the permit, regulation or code of practice referenced in this inspection record are for guidance and are not the official version. Please refer to the original permit, regulation or code of practice. To see the most up to date version of regulations and codes of practices please visit: http://www.bclaws.ca/						
	record o	r visit: http://ww	w2.gov.bc.ca/g	gov/topic.pa	noted on this inspection ge? ble%20Authorizations	
It is also important to note that this inspection record does not necessarily reflect each requirement or condition of the authorization therefore compliance is noted only for the requirements or conditions listed in the inspection record.						
Ministry of	Cariboo	Mailing	Address:	Phone:	(250) 398-4530	

Environment		400-640 Borland St	Fax: (250) 398-4214
	Environmental Protection	Williams Lake, BC V2G	Website:
	Division	4T1	http://www.gov.bc.ca/env