Regulated Party	Inspection No. Compliance Status	Receiving Environment	Response Code	Priority Rank	king Proactive and Reactive	Region	Type	Requirement Source	Waste Type
Huckleberry Mines Ltd.	19349 IN	Land	Notice	Medium	Proactive	Northern	Permit Conditions	Permit	Refuse
Mount Polley Mining Corporation	19386 IN	Surface water	Notice	Medium	Proactive	Southern	Permit Conditions	Permit	Effluent
Red Chris Development Company Ltd.	21426 IN	Air, Land	Notice	Low	Proactive	Northern		Code of Practice for Concrete and Concret	
Red Chris Development Company Ltd.	21427 IN	Air	Notice	Low	Proactive	Northern	Permit Conditions	Permit	Air
Red Chris Development Company Ltd.	21429 IN	Land, Surface water	Notice	Low	Proactive	Northern		Petroleum Storage and Distribution Facilit	
Mount Polley Mining Corporation	21685 IN	Surface water	Notice	High	Proactive	Southern	Permit Conditions	Permit	Effluent
Mount Polley Mining Corporation	18407 OUT	Surface water	Advisory	Medium	Reactive	Southern	Permit Conditions	Permit	Effluent
Mount Polley Mining Corporation	19552 OUT	Surface water	Advisory	Medium	Reactive	Southern	Permit Conditions	Permit	Effluent
Mount Polley Mining Corporation	19565 OUT	Surface water	Advisory	Medium	Reactive	Southern	Permit Conditions	Permit	Effluent
Huckleberry Mines Ltd.	20748 OUT	Air, Land	Advisory	High	Proactive	Northern	Permit Conditions	Permit	Refuse
luckleberry Mines Ltd.	21125 OUT	Air	Advisory	Low	Proactive	Northern	Permit Conditions	Permit	Air
ed Chris Development Company Ltd.	21425 OUT	Land, Surface water	Advisory	High	Proactive	Northern	Permit Conditions	Permit	Effluent
Red Chris Development Company Ltd.	21505 OUT	Land, Surface water	Advisory	Low	Proactive	Northern		Municipal Wastewater Regulation	Effluent
Mount Polley Mining Corporation	21927 OUT	Air	Advisory	High	Proactive	Southern	Permit Conditions	Permit Permit	Air
luckleberry Mines Ltd.	24268 OUT	Surface water	Advisory	High	Reactive	Northern	Permit Conditions	Permit	Effluent
Mount Polley Mining Corporation	24325 OUT	Surface water	Advisory	High	Proactive	Southern	Permit Conditions	Permit	Effluent
ed Chris Development Company Ltd.	20127 OUT	Land, Surface water	Warning	High	Proactive	Northern		Municipal Wastewater Regulation	Effluent
luckleberry Mines Ltd.	20749 OUT	Surface water	Warning	High	Proactive	Northern	Permit Conditions	Permit Permit	
ed Chris Development Company Ltd.	24365 OUT	Land, Surface water	Warning	High	Reactive	Northern		Permit	Effluent Effluent
luckleberry Mines Ltd.	19165 OUT	Land	Referred for Further Action	High	Reactive	Northern		Permit	Refuse

2015 - Impenal Metal Mines.

TOTAL INSPECTIONS - 20.

INCOMPLIANCE = 6 = 30% NONCOMPLIANT = 14 = 70%.

RECIEVED XIO ADVISORIES.

x3 WARNINGS.

XI REFERRED FOR FURTHER ACTION.

MPMC - 5 ADVISORIES, - WASTE TYPE - 4 EFFLUENT

HUCKLEBERRY - 3 ADVISORIES

I WARNING .

I FURTHER ACTION - REFUSE.

REDCHRIS - 2 ADVISORIES.

2 WARNINGS.